

SmartOTDR, T-BERD/MTS 2000v2, T-BERD/MTS 4000v2

Version ID: 11157

Release date : 15 February 2021

Version details

File System	21.6.3
Boot	V10.60
Linux Kernel	V21.4.1
Fiber Optics	V20.20
Instrument Setup	V20.20
Microscope	V20.20

Mainframe / Base Unit

New functionalities

- In a Job Manager sequence, add the ability to come back directly to the Job Manager main page after a connector inspection.

Problems corrections

- Correct application failure in presence of MPO switch module

OTDR

Improvements

- remove message “splitter not detected” when unknown splitter placed at fiber end in addition to the detected one.
- Reflectance pass/fail analysis removed from the unknown splitter event

Problems corrections

- Pdf report correctly updated after event type modification into SLM
- Application crash after stop/start during automatic configuration of the OTDR
- incorrect splitter direction of the last splitter icon for the Swisscom network configuration
- CABLE-SLM application crash when closing a project

C-/DWDM OTDR

Problems corrections

- T-BERD/MTS 2000V2 and 4000V2 lock up with CWDM OTDR module when running firmware version 18.50